

Engineering Technical Order

Date: December 20, 2011

SPG KVM Refresh, TDWR/SPG Modification Note 3

The KVM deployed in the SPG, RDA, and RPG cabinets are approaching the end of its lifecycle. The National Reconditioning Center (NRC) has noted a gradual increase in the field repair of these units over the past year due to continual wear. It is becoming more difficult to repair these units due to the lack of replacement parts. An SPG replacement model has been tested and selected as a compatible unit for the SPG cabinet configuration. The old KVM unit will be returned to the NRC to stock as spares for the WSR-88D RDA and RPG KVMs.

This modification only applies to SPG sites.

To view this modification document, click on the link below or copy and paste the URL in your web browser:

https://www.roc.noaa.gov/ssb/sysdoc/TDWR/disclaimer_iframe.asp?FILENAME=TDWR_SPG_mod3fnl.pdf