

Engineering Technical Order

Date: February 01, 2012

WSR-88D Hoists

This is an additional reminder to sites to perform the annual PMI Card 2-039 located in EHB 6-503-2 Revision 10 Change 3 dated 13 Feb 2012, before the Dual Polarization Team arrives on your site for the installation. It is imperative that all hoists are in excellent condition for this installation. The revised card with all of the new information is located on the ROC Web site at the link below.

The hard copy of Change 3 will be distributed in late February to Early March 2012.

<http://www.roc.noaa.gov/WSR88D/Program/MaintenanceManuals.aspx>