

Engineering Technical Order

Date: April 18, 2012

Replacement of AME Processor Circuit Card Assembly, Modification Note 148

The purpose of this modification is to replace the AME Processor CCA UD2A9A3. The present processor assembly contains defective firmware logic which does not allow the Flash AME function in System Test Software (STS) to work correctly.

With the new AME processor CCA installed, do not use the Flash AME function in STS until you have installed RDA Build 12.3 or Build 13.0 software. Attempting to flash the AME with RDA Build 12.0 or 12.1 software will totally corrupt the AME processor rendering it inoperative.

To view this modification document click on the link below or copy and paste the URL in your web browser:

http://www.roc.noaa.gov/ssb/sysdoc/techman/subs/DISCLAIMER_IFRAME.ASP?FILENAME=mod148fnl.pdf